HOU-XB5021 X-ray baggage scanner



Features:

- Economic model
- Double energy

Houper Group

- Built-in ARM CPU
- Energy saving design
- MTBF: More than 10000 hours
- With Digital Signal and Processor

X-ray machine technical parameters meet the technical conditions stipulated in the national standard "Micro Dose X-ray Security Inspection Equipment

Tunnel size(mm)	1000mm(L)*800mm(W)	
Conveyor Speed(m/s)	0.20(±10%)	
Conveyor height(mm)	341	
Conveyor Max Load(KG)	200	
Unit Weight(KG)	800	
Unit size	3138.5(L)*1295(W)*1716.5(H) mm	
Generator	140-160KV, oil cooling, from bottom to top	
Penetration	Typical 32mm steel, guarantee 30mm steel	
Wire Resolution	Typical AWG40, guarantee AWG38	
X-Ray dosage /inspection	Typical 1.0 μGy/h, guarantee 1.5 μGy/h	
Boundary Leakage	Typical 1.0 μGy/h, guarantee 1.5 μGy/h	
Power consumption	Max.1KVA	
Noise	<60dB	

website: www.Houper.com Email:info@Houper.com

218





E 856488300.10

Product Specifications:

Model: HOU-XB5021

Film Safety	Guarantee ASA/ISO1600 Film			
Computer	CPU: Cortex A9			
Display monitor	Dell or Acer, 17" LED screen, resolution 1280*1024			
Operation table	Single screen console			
Operation System	LINUX			
Image Enhancement	1-32times enlargement continuity, Color/BW, negative,high/low penetration, organic /inorganic, Stripping, general enhancement, and pseudo color,etc.			
Image Archive		At least 50,000 images stored automatically, enable transferring to USB disk, and converting to JPG, BMP, XF, PNG, TIFF, GIF six formats.		
Image Recall	All prece	All preceding images re-callable,retrieval.		
Other Functions	source s register	Fault diagnosis, system time setting, detection blind dots delete, x-ray source setting(analog or digital), alarm setting, images setting, software register, user management, TIP report, data setting(machine working time, x-ray source working time, baggage counter, etc.)		
Network Applications	Multiple remote applications available based on Ethernet LAN and windows platform, such as image centralized storage and identify, recheck workstation, and network TIP, etc (Optional).			
Operation temperature/Humidity		OC -45C/5%-95%(non-condensing)		
Storage temperature/Humidity		-40C = 70C / 5%-95%(non-condensing)		
Operation Power		220VAC(\pm 10%) 50 \pm 3Hz		
		100VAC,110VAC,120VAC,200VAC (optional)		





219

Houper Group website: www.Houper.com Email:info@Houper.com